

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
Telephone: (801) 538-5340
Fax: (801) 359-3940

RECEIVED

JAN 20 1994

DIVISION OF
OIL, GAS & MINING

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) 1/93 To (mo./yr.) 12/93
2. DOGM File Number (Mine No): S 053 / 027
3. Mine Name: Blackridge #1
4. Mineral(s) Mined (or permitted to mine): Picture Sandstone
5. Type of mine ☒ Surface Mine or ☐ Underground Mine
6. Legal Description (Location of Lands Affected):
1/4, SW 1/4, Section 18, Township 42 S, Range 14 W
1/4, 1/4, Section , Township , Range
1/4, 1/4, Section , Township , Range
7. Name of Operator or Company: Desert Landscapes
8. Permanent Street Address : 860 E 19th Street
City, State, Zip: Tucson AZ 85719
Phone: 602-623-1396
9. Company Representative (or designated operator):
Name: Joseph Cassetta
Title: President
Business Address: 860 E 19th Street
City, State, Zip: Tucson AZ 85719
Phone: 602-623-1396

☐ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was the mine active during the past year? Yes ☒ No ☐
2. If active, how much ore or mineral was mined? Approximately 100 tons

3. How much **additional acreage** was disturbed during the past year? 1/2 acre
4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.

Approximately 100 tons of Picture Sandstone was removed by the use of a Trackhoe and Front End Loader, disturbing approximately 1/2 acre.

5. How much acreage was **reclaimed** during the past year? Approximately 3/4 acre
6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.

Resculptured landscape by using the debris from mining Picture Sandstone. Results were good. Area was inspected and given the O.K. by the Bureau of Land Managment.

7. What is the **total disturbed acreage** at years end? Approximately 2 acres
8. Briefly summarize any mining and/or reclamation plans for the upcoming year.

Mining will start approximately the end of March.

A continuous resculpturing of previously mined areas will continue through the year.

NOTE: Section III., "Additional Information" applies only to **large mining operations**.

III. Additional Information

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.


Name (Typed or Print):

Joseph Cassetta

Title of Operator:

President

Signature of Operator:



Date:

1/17/94